

# Data Acquisition Setup for the Hadron and Muon Monitors

<u>Table of Contents</u>	<u>Page(s)</u>
The VME Front End.....	2
Hadron Monitor SWIC Scanner.....	3-4
Muon Monitor 1 SWIC Scanner.....	5-6
Muon Monitor 2 SWIC Scanner.....	7-8
Muon Monitor 3 SWIC Scanner.....	9-10
Gas Calibration Monitors SWIC Scanner.....	11-12

# The Front End: NMAAT

- The swic scanners for the hadron and muon monitors and the gas calibration chambers share the same front end.
- The Front End for the Hadron Muon Monitors and Gas Calibration chambers is NMAAT.
- To see the status (uptime) of the front end go to page D31. Click on “Select”. A box pops up, click on “System” and then on “No more”. Then the page should look like the one shown here.
- For information about the front end click on VME in the NMAAT line here.

## REBOOTING THE FRONT END

- To REBOOT the front end click on VME in the NMAAT line here.
- A box pops up. Click on “Reboot”. A box pops up. Enter a reason for the reboot.

PA D31 ACNET Node Poll<NoSets>

D31 ACNET Node Poll

Select Page Cull Radix STOP Search Edit Page Select

Show Query

Node	Address	Type	Uptime	p/s	Node	Address	Type	Uptime	p/s
E906MW	\$0A5D	VME	26D 23:42:55	0					
MWAP10	\$0B12	VME	132D 01:46:25	5					
MWDIPM	\$0BE4	VME	132D 01:47:56	1					
MWF2P3	\$0B4F	VME	133D 08:13:42	0					
MWIRE0	\$0A0B	VME	22D 03:41:27	24					
MWIRE1	\$0A59	VME	65D 18:20:19	1					
MWIRE2	\$0A5A	VME	7D 06:25:37	0					
MWIRE3	\$0A5B	VME	125D 08:34:37	19					
MWIRE5	\$0B44	VME	125D 01:58:11	0					
MWMB10	\$0B57	VME	8D 00:03:58	10					
MWMB12	\$0B5B	VME	8D 00:03:34	2					
MWMI20	\$0B5C	VME	125D 09:21:35	1					
MWMS1	\$0C01	VME	2D 05:26:17	2					
MWMTA	\$0A3E	VME	96D 05:11:01	1					
MWMB1	\$0C04	VME	125D 03:27:47	2					
NMAAT	\$0BE2	VME	71D 02:16:16	5					
MWIR65	\$0B0A	VME	125D 02:31:00	20					
SWIC	\$0A17	VME	105D 06:17:03	1					
SWICT	\$0AEB	VME	7D 06:52:41	2					

Messages

Reboot operation for node NMAAT aborted

Select returned 19 nodes

Select returned 19 nodes

Select returned 19 nodes

Select returned 19 nodes

# Hadron Monitor SWIC Scanner

- The swic scanner for the hadron monitor is NUMI\_HADM and can be accessed via page W115.
- Go to page W115, click "Swic". A box pops up, scroll down and click on NUMI\_HADM. The page will then look like the one shown here.

- The swic scanner is taking data when the Power is "ON" and the VME sequence is "ON", designated by "Seq On". If this says "Seq Off", turn the sequence on by clicking. (The hv may say that it is "on" or "off", either is fine, this doesn't matter.) By clicking on the REBOOT the swic scanner may be rebooted, this does not reboot the front end or any other swic scanner other than this one.

- The Measurement definitions must be set exactly as shown here. If the settings are different set them to the values shown here. Click on the "Type" entry, toggle it (by continuously clicking until "Slow" appears. Click on "Set" to set the value. Enter all other values by hand and click "Set" after each entry.

PA W115SWIC/MW TEST<NoSets>

W115 New Scanner Test Swic NUMI\_HADM (NMAAT) Pgm\_Tools

Configuration

Measurement Definitions

Read Set

#	Type	Gain (milsec)	Thres	Calc
0	Slow	1	16.666	10.000
1	Slow	1	16.666	10.000
2				
3				
4				
5				
6				
7				

Calculations

Calculation Definitions

Set to Default Delete

	mean	sigma	intensity	figure of merit
0	<M><S><I><F><Horz>	<1>	<48>	
1	<M><S><I><F><Vert>	<1>	<48>	
2				
3				
4				
5				
6				
7				

Sequence

current measurement number: 0

current measurement type: 0

Read Set

#	Type	Gain (milsec)	Thres	Calc
0	<0>	<Display>	none	none
1	<1>	<Display>	none	none
2	<?>	<none>	<none>	<none>
3	<?>	<none>	<none>	<none>
4	<?>	<none>	<none>	<none>
5	<?>	<none>	<none>	<none>
6	<?>	<none>	<none>	<none>
7	<?>	<none>	<none>	<none>
8	<?>	<none>	<none>	<none>
9	<?>	<none>	<none>	<none>
10	<?>	<none>	<none>	<none>
11	<?>	<none>	<none>	<none>
12	<?>	<none>	<none>	<none>
13	<?>	<none>	<none>	<none>
14	<?>	<none>	<none>	<none>
15	<?>	<none>	<none>	<none>
16	<?>	<none>	<none>	<none>
17	<?>	<none>	<none>	<none>
18	<?>	<none>	<none>	<none>

Events

Events

Read Set

Start Sample Stop

<AD> <FE> <FF>

External Events

External Events

MWIRE Status

Node # = 2

Power ON

Seq On

hv off

REBOOT

Plane out ( 0 )

Plot(DSP)

Calc Infor

Wire Data


Remove Hot Wire Yes

Auto Scale Plot Yes

Messages

SWIC test program started on console 114 (localhost)

# Hadron Monitor SWIC Scanner (contd.)


- The Events must be set as shown here. FE designates the use of External Events.
- Check that the External Events are set correctly....Clicking on "External Events" pops up this window. Check that the settings are the same as shown here.
- E:AATT4 and E:AATT5 are 2 different timer cards. The timer delays are set by hand, after entering the digits press enter on the keyboard. If the "E" is a "D" this means that the timer card is disabled. Enable it by clicking on the "D"; the "D" will turn into an "E".
- Check that the events in the timer card are set correctly.....Click the . A window pops up that looks like this for E:AATT4



- And this for E:AATT5



- E:AATT4 has AD as the trigger event and E:AATT5 has A9 as the trigger event. If need be, enter the proper event by hand and then press enter and then click "Close".



PA W115SWIC/MW TEST<NoSets>

W115

New Scanner Test (NMAAT)

Swic NUMI\_HADM

Pgm\_Tools

Configuration

Measurement Definitions

#	Type	Gain	Duration (milsec)	Thres	Calc
0	<Slow>	1	16,666	<10,000>	
1	<Slow>	1	16,666	<10,000>	
2	<X>	<X>	<X>	<X>	
3	<X>	<X>	<X>	<X>	
4	<X>	<X>	<X>	<X>	
5	<X>	<X>	<X>	<X>	
6	<X>	<X>	<X>	<X>	
7	<X>	<X>	<X>	<X>	

Calculations

Calculation Definitions

	mean,sigma,intensity,figure of merit	Delete
0	<M><S><I><F><Horz>	<1> <48>
1	<M><S><I><F><Vert>	<1> <48>
2	<X><X><X><X>	<X> <X>
3	<X><X><X><X>	<X> <X>
4	<X><X><X><X>	<X> <X>
5	<X><X><X><X>	<X> <X>
6	<X><X><X><X>	<X> <X>
7	<X><X><X><X>	<X> <X>

Sequence

current measurement number: 0

current measurement type: 0

#	Type	Gain	Duration (milsec)	Thres	Calc
0	<0>	<Display>	none	<none>	
1	<1>	<Display>	none	<none>	
2	<?>	<none>	<none>	<none>	
3	<?>	<none>	<none>	<none>	
4	<?>	<none>	<none>	<none>	
5	<?>	<none>	<none>	<none>	
6	<?>	<none>	<none>	<none>	
7	<?>	<none>	<none>	<none>	
8	<?>	<none>	<none>	<none>	
9	<?>	<none>	<none>	<none>	
10	<?>	<none>	<none>	<none>	
11	<?>	<none>	<none>	<none>	
12	<?>	<none>	<none>	<none>	
13	<?>	<none>	<none>	<none>	
14	<?>	<none>	<none>	<none>	
15	<?>	<none>	<none>	<none>	
16	<?>	<none>	<none>	<none>	
17	<?>	<none>	<none>	<none>	
18	<?>	<none>	<none>	<none>	

Events

Events

	Start	Sample	Stop
<AD>	<FE>	<FF>	

External Events

External Events

Timers

	Timer	Value	Unit	Event
E:AATT4	1100000	USEC	E	
E:AATT5	10	USEC	E	

MWIRE Status

Node # = 2

Power ON

Seq On

hv off

REBOOT

Plane out ( 0)

Plot(DSP)

Calc Infor

Wire Data

Remove Hot Wire

Auto Scale Plot

Messages

SWIC test program started on console 114 (localhost)

# Muon Monitor 1 SWIC Scanner

- The swic scanner for the hadron monitor is NUMI\_MMA1 and can be accessed via page W115.
- Go to page W115, click "Swic". A box pops up, scroll down and click on NUMI\_MMA1. The page will then look like the one shown here.

- The swic scanner is taking data when the Power is "ON" and the VME sequence is "ON", designated by "Seq On". If this says "Seq Off", turn the sequence on by clicking. (The hv may say that it is "on" or "off", either is fine, this doesn't matter.) By clicking on the REBOOT the swic scanner may be rebooted, this does not reboot the front end or any other swic scanner other than this one.

- The Measurement definitions must be set exactly as shown here. If the settings are different set them to the values shown here. Click on the "Type" entry, toggle it (by continuously clicking until "Slow" appears. Click on "Set" to set the value. Enter all other values by hand and click "Set" after each entry.

PA W115SWIC/MW TEST<NoSets>

W115 New Scanner Test Swic NUMI\_MMA1 (NMAAT) Pgm\_Tools

Configuration

Measurement Definitions

Read Set

#	Type	Gain (milsec)	Thres	Calc
0	Slow	1	16.666	10.000
1	Slow	1	16.666	10.000
2				
3				
4				
5				
6				
7				

Calculations

Calculation Definitions

Set to Default Delete

	mean	sigma	intensity	figure of merit
0	<M><S><I><F><Horz>	<1>	<48>	
1	<M><S><I><F><Vert>	<1>	<48>	
2	<X><X><X><X>	<X>	<X>	
3	<X><X><X><X>	<X>	<X>	
4	<X><X><X><X>	<X>	<X>	
5	<X><X><X><X>	<X>	<X>	
6	<X><X><X><X>	<X>	<X>	
7	<X><X><X><X>	<X>	<X>	

Sequence

current measurement number: 0

current measurement type: 0

Read Set

	Type	Gain	Thres	Calc
0	<0>	<Display>	none	none
1	<1>	<Display>	none	none
2	<?>	<none>	<none>	<none>
3	<?>	<none>	<none>	<none>
4	<?>	<none>	<none>	<none>
5	<?>	<none>	<none>	<none>
6	<?>	<none>	<none>	<none>
7	<?>	<none>	<none>	<none>
8	<?>	<none>	<none>	<none>
9	<?>	<none>	<none>	<none>
10	<?>	<none>	<none>	<none>
11	<?>	<none>	<none>	<none>
12	<?>	<none>	<none>	<none>
13	<?>	<none>	<none>	<none>
14	<?>	<none>	<none>	<none>
15	<?>	<none>	<none>	<none>
16	<?>	<none>	<none>	<none>
17	<?>	<none>	<none>	<none>
18	<?>	<none>	<none>	<none>

Events

Events

Read Set

Start Sample Stop

<AD> <FE> <FF>

External Events

External Events

MWIRE Status

Node # = 3

Power ON

Seq On

HV On

REBOOT

Plane in ( 2 )

Plot(DSP)

Calc Infor

Wire Data


Remove Hot Wire Yes

Auto Scale Plot Yes

Messages


SWIC test program started on console 114 (localhost)

# Muon Monitor 1 SWIC Scanner (contd.)


- The Events must be set as shown here. FE designates the use of External Events.
- Check that the External Events are set correctly....Clicking on "External Events" pops up this window. Check that the settings are the same as shown here.
- E:AATT6 and E:AATT7 are 2 different timer cards. The timer delays are set by hand, after entering the digits press enter on the keyboard. If the "E" is a "D" this means that the timer card is disabled. Enable it by clicking on the "D"; the "D" will turn into an "E".
- Check that the events in the timer card are set correctly.....Click the . A window pops up that looks like this for E:AATT6



- And this for E:AATT7



- E:AATT6 has AD as the trigger event and E:AATT7 has A9 as the trigger event. If need be, enter the proper event by hand and then press enter and then click "Close".



PA W115SWIC/MW TEST<NoSets>

New Scanner Test (NMAAT)

Swic NUMI\_MMA1

Pgm\_Tools

Configuration

Measurement Definitions

#	Type	Gain	Duration (milsec)	Thres	Calc
0	<Slow>	<1>	<16,666>	<10,000>	<Set>
1	<Slow>	<1>	<16,666>	<10,000>	<Set>
2	<X>	<X>	<X>	<X>	<Set>
3	<X>	<X>	<X>	<X>	<Set>
4	<X>	<X>	<X>	<X>	<Set>
5	<X>	<X>	<X>	<X>	<Set>
6	<X>	<X>	<X>	<X>	<Set>
7	<X>	<X>	<X>	<X>	<Set>

Calculations

Calculation Definitions

#	mean,sigma,intensity,figure of merit	Delete
0	<M><S><I><F><Horz>	<1> <48>
1	<M><S><I><F><Vert>	<1> <48>
2	<X><X><X><X>	<X> <X>
3	<X><X><X><X>	<X> <X>
4	<X><X><X><X>	<X> <X>
5	<X><X><X><X>	<X> <X>
6	<X><X><X><X>	<X> <X>
7	<X><X><X><X>	<X> <X>

Sequence

current measurement number: 0

current measurement type: 0

#	Type	Gain	Duration (milsec)	Thres	Calc
0	<0>	<Display>	<none>	<none>	<Set>
1	<1>	<Display>	<none>	<none>	<Set>
2	<?>	<none>	<none>	<none>	<Set>
3	<?>	<none>	<none>	<none>	<Set>
4	<?>	<none>	<none>	<none>	<Set>
5	<?>	<none>	<none>	<none>	<Set>
6	<?>	<none>	<none>	<none>	<Set>
7	<?>	<none>	<none>	<none>	<Set>
8	<?>	<none>	<none>	<none>	<Set>
9	<?>	<none>	<none>	<none>	<Set>
10	<?>	<none>	<none>	<none>	<Set>
11	<?>	<none>	<none>	<none>	<Set>
12	<?>	<none>	<none>	<none>	<Set>
13	<?>	<none>	<none>	<none>	<Set>
14	<?>	<none>	<none>	<none>	<Set>
15	<?>	<none>	<none>	<none>	<Set>
16	<?>	<none>	<none>	<none>	<Set>
17	<?>	<none>	<none>	<none>	<Set>
18	<?>	<none>	<none>	<none>	<Set>

Events

Events

#	Type	Gain	Duration (milsec)	Thres	Calc
0	<Start>	<Sample>	<Stop>	<Set>	<Set>
1	<AD>	<FE>	<FF>	<Set>	<Set>

External Events

External Events

#	Type	Gain	Duration (milsec)	Thres	Calc
0	<E:AATT6>	<1100000>	<USEC>	<E>	<Set>
1	<E:AATT7>	<10>	<USEC>	<E>	<Set>

Timers

E:AATT6 [ 1100000 ] USEC E

E:AATT7 [ 10 ] USEC E

MWIRE Status

Node # = 3

Power ON

Seq On

HV On

REBOOT

Plane In ( 2 )

Plot(DSP)

Calc Infor

Wire Data

Remove Hot Wire Yes

Auto Scale Plot Yes

Messages

SWIC test program started on console 114 (localhost)



# Muon Monitor 2 SWIC Scanner

- The swic scanner for the hadron monitor is NUMI\_MMA2 and can be accessed via page W115.
- Go to page W115, click "Swic". A box pops up, scroll down and click on NUMI\_MMA2. The page will then look like the one shown here.

- The swic scanner is taking data when the Power is "ON" and the VME sequence is "ON", designated by "Seq On". If this says "Seq Off", turn the sequence on by clicking. (The hv may say that it is "on" or "off", either is fine, this doesn't matter.) By clicking on the REBOOT the swic scanner may be rebooted, this does not reboot the front end or any other swic scanner other than this one.

- The Measurement definitions must be set exactly as shown here. If the settings are different set them to the values shown here. Click on the "Type" entry, toggle it (by continuously clicking until "Slow" appears. Click on "Set" to set the value. Enter all other values by hand and click "Set" after each entry.

PA W115SWIC/MW TEST<NoSets>

New Scanner Test Swic NUMI\_MMA2 (NMAAT) Pgm\_Tools

Configuration

Measurement Definitions

Read Set

#	Type	Gain (milsec)	Thres	Calc
0	Slow	1	16.666	10.000
1	Slow	1	16.666	10.000
2				
3				
4				
5				
6				
7				

Calculations

Calculation Definitions

Set to Default Delete

	mean	sigma	intensity	figure of merit
0	<M><S><I><F><Horz>	<1>	<48>	
1	<M><S><I><F><Vert>	<1>	<48>	
2	<X><X><X><X>	<X>	<X>	
3	<X><X><X><X>	<X>	<X>	
4	<X><X><X><X>	<X>	<X>	
5	<X><X><X><X>	<X>	<X>	
6	<X><X><X><X>	<X>	<X>	
7	<X><X><X><X>	<X>	<X>	

Sequence

current measurement number: 0

current measurement type: 0

Read Set

#	Type	Gain (milsec)	Thres	Calc
0	<0>	<Display>	none	none
1	<1>	<Display>	none	none
2	<?>	<none>	<none>	<none>
3	<?>	<none>	<none>	<none>
4	<?>	<none>	<none>	<none>
5	<?>	<none>	<none>	<none>
6	<?>	<none>	<none>	<none>
7	<?>	<none>	<none>	<none>
8	<?>	<none>	<none>	<none>
9	<?>	<none>	<none>	<none>
10	<?>	<none>	<none>	<none>
11	<?>	<none>	<none>	<none>
12	<?>	<none>	<none>	<none>
13	<?>	<none>	<none>	<none>
14	<?>	<none>	<none>	<none>
15	<?>	<none>	<none>	<none>
16	<?>	<none>	<none>	<none>
17	<?>	<none>	<none>	<none>
18	<?>	<none>	<none>	<none>

Events

Events

Read Set

Start Sample Stop

<AD> <FE> <FF>

External Events

External Events

MWIRE Status

Node # = 4

Power ON

Seq On

HV On

REBOOT

Plane out ( 0)

Plot(DSP)

Calc Infor

Wire Data


Remove Hot Wire Yes

Auto Scale Plot Yes

Messages

SWIC test program started on console 114 (localhost)

# Muon Monitor 2 SWIC Scanner (contd.)

- The Events must be set as shown here. FE designates the use of External Events.
- Check that the External Events are set correctly....Clicking on "External Events" pops up this window. Check that the settings are the same as shown here.
- E:AATT6 and E:AATT7 are 2 different timer cards. The timer delays are set by hand, after entering the digits press enter on the keyboard. If the "E" is a "D" this means that the timer card is disabled. Enable it by clicking on the "D"; the "D" will turn into an "E".
- Check that the events in the timer card are set correctly.....Click the . A window pops up that looks like this for E:AATT6



- And this for E:AATT7



- E:AATT6 has AD as the trigger event and E:AATT7 has A9 as the trigger event. If need be, enter the proper event by hand and then press enter and then click "Close".

PA W115SWIC/MW TEST<NoSets>

New Scanner Test (NMAAT)

Swic NUMI\_MMA2

Pgm\_Tools

Configuration

Measurement Definitions

#	Type	Gain	Duration (milsec)	Thres	Calc
0	<Slow>	1	16,666	<10,000>	<FE>
1	<Slow>	1	16,666	<10,000>	<FE>
2	<X>	<X>	<X>	<X>	<X>
3	<X>	<X>	<X>	<X>	<X>
4	<X>	<X>	<X>	<X>	<X>
5	<X>	<X>	<X>	<X>	<X>
6	<X>	<X>	<X>	<X>	<X>
7	<X>	<X>	<X>	<X>	<X>

Calculations

Calculation Definitions

#	Type	Gain	Duration (milsec)	Thres	Calc
0	<M>	<S>	<I>	<F>	<Horz>
1	<M>	<S>	<I>	<F>	<Vert>
2	<X>	<X>	<X>	<X>	<X>
3	<X>	<X>	<X>	<X>	<X>
4	<X>	<X>	<X>	<X>	<X>
5	<X>	<X>	<X>	<X>	<X>
6	<X>	<X>	<X>	<X>	<X>
7	<X>	<X>	<X>	<X>	<X>

Sequence

current measurement number: 0

current measurement type: 0

#	Type	Gain	Duration (milsec)	Thres	Calc
0	<0>	<Display>	<none>	<none>	<none>
1	<1>	<Display>	<none>	<none>	<none>
2	<?>	<none>	<none>	<none>	<none>
3	<?>	<none>	<none>	<none>	<none>
4	<?>	<none>	<none>	<none>	<none>
5	<?>	<none>	<none>	<none>	<none>
6	<?>	<none>	<none>	<none>	<none>
7	<?>	<none>	<none>	<none>	<none>
8	<?>	<none>	<none>	<none>	<none>
9	<?>	<none>	<none>	<none>	<none>
10	<?>	<none>	<none>	<none>	<none>
11	<?>	<none>	<none>	<none>	<none>
12	<?>	<none>	<none>	<none>	<none>
13	<?>	<none>	<none>	<none>	<none>
14	<?>	<none>	<none>	<none>	<none>
15	<?>	<none>	<none>	<none>	<none>
16	<?>	<none>	<none>	<none>	<none>
17	<?>	<none>	<none>	<none>	<none>
18	<?>	<none>	<none>	<none>	<none>

Events

Events

#	Type	Gain	Duration (milsec)	Thres	Calc
0	<Start>	<Sample>	<Stop>	<FE>	<FE>
1	<AD>	<FE>	<FF>	<FE>	<FE>

External Events

External Events

#	Type	Gain	Duration (milsec)	Thres	Calc
0	<E:AATT6>	<1100000>	<USEC>	<E>	<E>
1	<E:AATT7>	<10>	<USEC>	<E>	<E>

Timers

Restore

MWIRE Status

Node # = 4

Power ON

Seq On

HV On

REBOOT

Plane out ( 0)

Plot(DSP)

Calc Infor

Wire Data

Remove Hot Wire

Auto Scale Plot

Messages

SWIC test program started on console 114 (localhost)



# Muon Monitor 3 SWIC Scanner

- The swic scanner for the hadron monitor is NUMI\_MMA3 and can be accessed via page W115.
- Go to page W115, click "Swic". A box pops up, scroll down and click on NUMI\_MMA3. The page will then look like the one shown here.

- The swic scanner is taking data when the Power is "ON" and the VME sequence is "ON", designated by "Seq On". If this says "Seq Off", turn the sequence on by clicking. (The hv may say that it is "on" or "off", either is fine, this doesn't matter.) By clicking on the REBOOT the swic scanner may be rebooted, this does not reboot the front end or any other swic scanner other than this one.

- The Measurement definitions must be set exactly as shown here. If the settings are different set them to the values shown here. Click on the "Type" entry, toggle it (by continuously clicking until "Slow" appears. Click on "Set" to set the value. Enter all other values by hand and click "Set" after each entry.

PA W115SWIC/MW TEST<NoSets>

W115 New Scanner Test Swic NUMI\_MMA3 (NMAAT) Pgm\_Tools

Configuration

Measurement Definitions

Read Set

#	Type	Gain (milsec)	Thres	Calc
0	Slow	1	16.666	10.000
1	Slow	1	16.666	10.000
2				
3				
4				
5				
6				
7				

Calculations

Calculation Definitions

Set to Default Delete

	mean	sigma	intensity	figure of merit
0	<M><S><I><F><Horz>	<1>	<48>	
1	<M><S><I><F><Vert>	<1>	<48>	
2				
3				
4				
5				
6				
7				

Sequence

current measurement number: 0

current measurement type: 0

Read Set

#	Type	Gain (milsec)	Thres	Calc
0	<0>	<Display>	none	none
1	<1>	<Display>	none	none
2	<?>	<none>	<none>	<none>
3	<?>	<none>	<none>	<none>
4	<?>	<none>	<none>	<none>
5	<?>	<none>	<none>	<none>
6	<?>	<none>	<none>	<none>
7	<?>	<none>	<none>	<none>
8	<?>	<none>	<none>	<none>
9	<?>	<none>	<none>	<none>
10	<?>	<none>	<none>	<none>
11	<?>	<none>	<none>	<none>
12	<?>	<none>	<none>	<none>
13	<?>	<none>	<none>	<none>
14	<?>	<none>	<none>	<none>
15	<?>	<none>	<none>	<none>
16	<?>	<none>	<none>	<none>
17	<?>	<none>	<none>	<none>
18	<?>	<none>	<none>	<none>

Events

Events

Read Set

Start Sample Stop

<AD> <FE> <FF>

External Events

External Events

MWIRE Status

Node # = 5

Power ON

Seq On

hw off

REBOOT

Plane out ( 0)

Plot(DSP)

Calc Infor

Wire Data


Remove Hot Wire Yes

Auto Scale Plot Yes

Messages

SWIC test program started on console 114 (localhost)

# Muon Monitor 3 SWIC Scanner (contd.)

- The Events must be set as shown here. FE designates the use of External Events.
- Check that the External Events are set correctly....Clicking on "External Events" pops up this window. Check that the settings are the same as shown here.
- E:AATT6 and E:AATT7 are 2 different timer cards. The timer delays are set by hand, after entering the digits press enter on the keyboard. If the "E" is a "D" this means that the timer card is disabled. Enable it by clicking on the "D"; the "D" will turn into an "E".
- Check that the events in the timer card are set correctly.....Click the . A window pops up that looks like this for E:AATT6



- And this for E:AATT7



- E:AATT6 has AD as the trigger event and E:AATT7 has A9 as the trigger event. If need be, enter the proper event by hand and then press enter and then click "Close".

PA W115SWIC/MW TEST<NoSets>

New Scanner Test (NMAAT)

Swic NUMI\_MMA3

Pgm\_Tools

Configuration

Measurement Definitions

#	Type	Gain	Duration (milsec)	Thres	Calc
0	<Slow>	<1>	<16,666>	<10,000>	<Set>
1	<Slow>	<1>	<16,666>	<10,000>	<Set>
2	<X>	<X>	<X>	<X>	<Set>
3	<X>	<X>	<X>	<X>	<Set>
4	<X>	<X>	<X>	<X>	<Set>
5	<X>	<X>	<X>	<X>	<Set>
6	<X>	<X>	<X>	<X>	<Set>
7	<X>	<X>	<X>	<X>	<Set>

Calculations

Calculation Definitions

#	mean,sigma,intensity,figure of merit	Delete
0	<M><S><I><F><Horz>	<1> <48>
1	<M><S><I><F><Vert>	<1> <48>
2	<X><X><X><X>	<X> <X>
3	<X><X><X><X>	<X> <X>
4	<X><X><X><X>	<X> <X>
5	<X><X><X><X>	<X> <X>
6	<X><X><X><X>	<X> <X>
7	<X><X><X><X>	<X> <X>

Sequence

current measurement number: 0

current measurement type: 0

#	Type	Gain	Duration (milsec)	Thres	Calc
0	<0>	<Display>	<none>	<none>	<Set>
1	<1>	<Display>	<none>	<none>	<Set>
2	<?>	<none>	<none>	<none>	<Set>
3	<?>	<none>	<none>	<none>	<Set>
4	<?>	<none>	<none>	<none>	<Set>
5	<?>	<none>	<none>	<none>	<Set>
6	<?>	<none>	<none>	<none>	<Set>
7	<?>	<none>	<none>	<none>	<Set>
8	<?>	<none>	<none>	<none>	<Set>
9	<?>	<none>	<none>	<none>	<Set>
10	<?>	<none>	<none>	<none>	<Set>
11	<?>	<none>	<none>	<none>	<Set>
12	<?>	<none>	<none>	<none>	<Set>
13	<?>	<none>	<none>	<none>	<Set>
14	<?>	<none>	<none>	<none>	<Set>
15	<?>	<none>	<none>	<none>	<Set>
16	<?>	<none>	<none>	<none>	<Set>
17	<?>	<none>	<none>	<none>	<Set>
18	<?>	<none>	<none>	<none>	<Set>

Events

Events

#	Type	Gain	Duration (milsec)	Thres	Calc
0	<0>	<Start>	<Sample>	<Stop>	<Set>
1	<1>	<AD>	<FE>	<FF>	<Set>

External Events

External Events

#	Type	Gain	Duration (milsec)	Thres	Calc
0	<0>	<AD>	<FE>	<FF>	<Set>
1	<1>	<AD>	<FE>	<FF>	<Set>

Timers

#	Type	Gain	Duration (milsec)	Thres	Calc
0	<0>	<AD>	<FE>	<FF>	<Set>
1	<1>	<AD>	<FE>	<FF>	<Set>

MWIRE Status

Node # = 5

Power ON

Seq On

hv off

REBOOT

Plane out ( 0)

Plot(DSP)

Calc Infor

Wire Data

Remove Hot Wire

Auto Scale Plot

Messages

SWIC test program started on console 114 (localhost)

# Gas Calibration SWIC Scanner

- The swic scanner for the hadron monitor is NUMI\_MGSM and can be accessed via page W115.
- Go to page W115, click "Swic". A box pops up, scroll down and click on NUMI\_MGSM. The page will then look like the one shown here.

- The swic scanner is taking data when the Power is "ON" and the VME sequence is "ON", designated by "Seq On". If this says "Seq Off", turn the sequence on by clicking. (The hv may say that it is "on" or "off", either is fine, this doesn't matter.) By clicking on the REBOOT the swic scanner may be rebooted, this does not reboot the front end or any other swic scanner other than this one.

- The Measurement definitions must be set exactly as shown here. If the settings are different set them to the values shown here. Click on the "Type" entry, toggle it (by continuously clicking until "Slow" appears. Click on "Set" to set the value. Enter all other values by hand and click "Set" after each entry.

PA W115SWIC/MW TEST<NoSets>

W115 New Scanner Test Swic NUMI\_MGSM (NMAAT) Pgm\_Tools

Configuration

Measurement Definitions

Read Set

#	Type	Gain (milsec)	Thres	Calc
0	Slow	1	500	10,000
1	Slow	1	500	10,000
2				
3				
4				
5				
6				
7				

Calculations

Calculation Definitions

Set to Default Delete

	mean	sigma	intensity	figure of merit
0	<M><S><I><F><Horz>	<1>	<48>	
1	<M><S><I><F><Vert>	<1>	<48>	
2				
3				
4				
5				
6				
7				

Sequence

current measurement number: 1  
current measurement type: 1

Read Set

#	Type	Gain (milsec)	Thres	Calc
0	<0>	<Display>	none	none
1	<1>	<Display>	none	none
2	<?>	<none>	<none>	<none>
3	<?>	<none>	<none>	<none>
4	<?>	<none>	<none>	<none>
5	<?>	<none>	<none>	<none>
6	<?>	<none>	<none>	<none>
7	<?>	<none>	<none>	<none>
8	<?>	<none>	<none>	<none>
9	<?>	<none>	<none>	<none>
10	<?>	<none>	<none>	<none>
11	<?>	<none>	<none>	<none>
12	<?>	<none>	<none>	<none>
13	<?>	<none>	<none>	<none>
14	<?>	<none>	<none>	<none>
15	<?>	<none>	<none>	<none>
16	<?>	<none>	<none>	<none>
17	<?>	<none>	<none>	<none>
18	<?>	<none>	<none>	<none>

Events

Events

Read Set

	Start	Sample	Stop
	<AD>	<FE>	<FF>

External Events

External Events

MWIRE Status

Node # = 6

Power ON

Seq On

HV On

REBOOT

Plane in ( 2 )

Plot(DSP)

Calc Infor

Wire Data


Remove Hot Wire Yes


Auto Scale Plot Yes

Messages

SWIC test program started on console 114 (localhost)

# Gas Calibration SWIC Scanner (contd.)

- The Events must be set as shown here. FE designates the use of External Events.
- Check that the External Events are set correctly....Clicking on "External Events" pops up this window. Check that the settings are the same as shown here.
- E:AATT2 and E:AATT3 are 2 different timer cards. The timer delays are set by hand, after entering the digits press enter on the keyboard. If the "E" is a "D" this means that the timer card is disabled. E:AATT3 is not used. Only E:AATT2 should be enabled, "E". Enable it by clicking on the "D"; the "D" will turn into an "E".
- Check that the events in the timer card are set correctly.....Click the . A window pops up that looks like this for E:AATT2



- E:AATT2 has AD as the trigger event. If need be, enter the proper event by hand and then press enter and then click "Close".

PA W115SWIC/MW TEST<NoSets>

W115 New Scanner Test (NMAAT) Swic NUMI\_MGSM Pgm\_Tools

**Configuration**

Measurement Definitions

#	Type	Gain	Duration (milsec)	Thres	Calc
0	<Slow>	<1>	<500>	<10,000>	<Set>
1	<Slow>	<1>	<500>	<10,000>	<Set>
2	<X>	<X>	<X>	<X>	<Set>
3	<X>	<X>	<X>	<X>	<Set>
4	<X>	<X>	<X>	<X>	<Set>
5	<X>	<X>	<X>	<X>	<Set>
6	<X>	<X>	<X>	<X>	<Set>
7	<X>	<X>	<X>	<X>	<Set>

**Calculations**

Calculation Definitions

	mean,sigma,intensity,figure of merit	Delete
0	<M><S><I><F><Horz>	<1> <48>
1	<M><S><I><F><Vert>	<1> <48>
2	<X><X><X><X>	<X> <X>
3	<X><X><X><X>	<X> <X>
4	<X><X><X><X>	<X> <X>
5	<X><X><X><X>	<X> <X>
6	<X><X><X><X>	<X> <X>
7	<X><X><X><X>	<X> <X>

**Sequence**

current measurement number: 1  
current measurement type: 1

#	Type	Gain	Duration (milsec)	Thres	Calc
0	<0>	<Display>	<none>	<none>	<Set>
1	<1>	<Display>	<none>	<none>	<Set>
2	<?>	<none>	<none>	<none>	<Set>
3	<?>	<none>	<none>	<none>	<Set>
4	<?>	<none>	<none>	<none>	<Set>
5	<?>	<none>	<none>	<none>	<Set>
6	<?>	<none>	<none>	<none>	<Set>
7	<?>	<none>	<none>	<none>	<Set>
8	<?>	<none>	<none>	<none>	<Set>
9	<?>	<none>	<none>	<none>	<Set>
10	<?>	<none>	<none>	<none>	<Set>
11	<?>	<none>	<none>	<none>	<Set>
12	<?>	<none>	<none>	<none>	<Set>
13	<?>	<none>	<none>	<none>	<Set>
14	<?>	<none>	<none>	<none>	<Set>
15	<?>	<none>	<none>	<none>	<Set>
16	<?>	<none>	<none>	<none>	<Set>
17	<?>	<none>	<none>	<none>	<Set>
18	<?>	<none>	<none>	<none>	<Set>

**Events**

Events

	Start	Sample	Stop
<AD>	<FE>	<FF>	

**External Events**

External Events

**Timers**

Timer	Value	Unit	Event
E:AATT2	100000	USEC	E
E:AATT3	0	USEC	D

**MWIRE Status**

Node # = 6  
Power ON  
Seq On  
HV On  
REBOOT  
Plane In ( 2)

**Messages**

SWIC test program started on console 114 (localhost)